

HIMACHAL PRADESH
PUBLIC WORKS DEPARTMENT


No.PWN/CB/WA/School Building/2026-27- 749-50 Dated:- 6 -05-2026.
To

The President,
Vidyavati International School Malkwal,
Tehsil-Nurpur, Distt.-Kangra (H.P).


Subject: - Regarding School Building Safety Certificate.


Enclosed please find herewith School Building Safety Certificate
for the financial year 2026-27 for favor of further necessary action please.

DA/Certificate.


Executive Engineer,
Nurpur Division, HPPWD,
Nurpur.

Copy to The Assistant Engineer, Sub-Division, Suliali HPPWD,
for information w.r.t. his office letter No.41 dated 05-05-2026.



Executive Engineer,
Nurpur Division, HPPWD,
Nurpur.





CERTIFICATE


The Inspection of school building of Vidyavati International School Malkwal in Tehsil Nurpur Distt Kangra (H.P) has been conducted by the Assistant Engineer on 30/04/2026 Sub Division, HPPWD., Suliali accompanied with Junior Engineer. On the basis of their inspection report, it has been found that no Earthquakes resistant norms have been adopted for the construction of School building. No structural drawing approved by the competent government agency were produced by the school authority. The structure of the building is a non Engineering structure. Hence, the structural safety of building can't be ensured specially from Earthquake point of view. This Department will not responsible for any type of loss of life and property etc., if this structure fails under any circumstances.

However, as per visual inspection, the building appears to be safe and accordingly, the Building Safety Certificate is being issued by this Department from 01.04.2026 to 31.03.2027. This Department could not assess the structural safety of said building as the same was not constructed under the supervision of this Department.


Junior Engineer,
Section Suliali


Assistant Engineer
Suliali Sub-Division, HPPWD.,
Suliali.


Executive Engineer
Nurpur Division HPPWD.,
Nurpur.



Annexure C

PERFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. **103**

Dated: **18-04-2026**

It is certified that an inspection team headed by Assistant Engineer from Jal Shakti Vibhag Sub Division Nurpur inspected that Vidyavati international School Vill. Malkawal PO Khuwara Tehsil Nurpur Distt. Kangra HP on **18/4/2026** checked that water test report submitted by the school and found that the school has potable drinking water for students and staff of the institution and is having provision for running water in the toilets and is maintaining the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/ State U.T. Govt.

The above is valid for a period of One Year

Signature with Seal:

Mohinder Singh
Assistant Engineer,
Jal Shakti, Sub-Division
Nurpur (Kangra) H.P.

Name :

Mohinder Singh

Designation :

Assistant Engineer

Name & Address of the Office/Department.....

To

Vidyavati International School
Vill Malkwal PO Khuwara
Tehsil Nurpur Distt. Kangra H.P.



**HIMACHAL PRADESH
JAL SHAKTI VIBHAG**

REPORT ON PHYSICAL / CHEMICAL & BACTERIOLOGICAL EXAMINATION OF WATER SAMPLE
 LAB NAME:- JS Lab Nurpur
 P/C & BACT NO.:- 1 (School Samples)
 SENDER'S ADDRESS :- Smt. Vandana Pathania ,President Vidyavati International School, Malkwal Teh.
 Nurpur Distt. Kangra (H.P.)
 DATE & TIME OF COLLECTION W/S :- 13.04.2026,
 NAME OF SCHEME/SOURCE :-LWSS Mamooch Gurchal Niar
 DIV.:- Nurpur
 SUB. DIV.:- Nurpur
 DATED :- 18/04/2026
 9.00 A M.


BLOCK :- Nurpur		G P :- Theher			
VILL :- Malkwal		HABITATION: - Tap From School Complex			
DATE & TIME OF ARIVAL AT LAB		13/04/2026, 11:00AM			
DATE & TIME OF W/S EXAMINATION		- do -			
Sr No.	PARAMETER TYPE	QUALITY PARAMETER	BIS DESIRABLE LIMIT (P.P.M.)Req.as per BIS 10500:2012	BIS PERMISSIBLE LIMIT (P.P.M.)Req.as per BIS 10500:2012	ACTUAL LEVEL (P.P.M)/mg/ l
1	CHEMICAL	FLUORIDE	1.0	1.5	0.0
2	do	ALKALINITY	200	600	220
3	do	HARDNESS	200	600	240
4	do	CALICIUM	75	200	56.0
5	do	MEGNESIUM	30	100	24.3
6	do	T.D.S.	500	2000	320
7	do	IRON	1	No Relaxation	0.00
8	do	CHLORIDE	250	1000	26
9	do	RESEDUAL CHLORINE	0.2	1.0	0.0
10	do	NITRATE	45	No Relaxation	Nil
11	do	SULPHATE	200	400	---
12	PHYSICAL	TURBIDITY	1 N.T.U	5 N.T.U	0.46 NTU
13	OTHER	p/H	6.5 to 8.5	No Relaxation	7.76


BACTERIOLOGICAL EXAMINATION


M.P.N. TOTAL COLIFORMS : At 37 degree centigrade, for 48 hours in Mac-Conkey broth culture media	Nil /per 100 ml.
M.P.N OF FAECAL COLIFORMS :	--/per 100ml.
M.P.N of E. Coli :	--/.per 100ml.

Note: - Coli form count should be zero in any sample of 100 ml. from water entering the distribution system.

RAMARKS:- As of water sample tested, the parameters within limit.


 Assistant Chemist
 Water Testing Lab,
 Nurpur Distt. Kangra(H.P.)




 Assistant Engineer
 Jal Shakti Vibhag Sub division,
 Nurpur Distt. Kangra(H.P.)



Single Window Clearance System

Directorate of Industries (DOI)
Govt. of Himachal Pradesh

DIRECTORATE OF FIRE SERVICES HIMACHAL PRADESH SHIMLA-2

NO OBJECTION CERTIFICATE


TO WHOM IT MAY CONCERN

That the premises of VIDYAVATI INTERNATIONAL SCHOOL MALKWAL, NURPUR TEH. NURPUR DISTT. KANGRA H.P. was inspected on 30 May, 2025 with reference to his Registration No. HP-FIRE/121249 under Application ID: 121249 dated 02 Jun, 2025 by the incharge Fire Station FP Nurpur with regard to measures adopted for protection against fire and it has been reported/recommended.

That the First Aid Fire Fighting measures adopted by the above applicant at his premises were found satisfactory at the time of inspection. Hence, No Objection Certificate is issued/ renewed for two years w.e.f. 06 Jun, 2025 to 05 Jun, 2027 subject to fulfilment of the following conditions:-

1. That each individual working on the above premises must be trained to handle/operate fire fighting equipment/system installed therein.
2. That it shall be the responsibility of the above named applicant to maintain the fire fighting equipment/system in perfect running condition, failing which this certificate shall be treated as cancelled.
3. Mock Drill shall be conducted in accordance with fire safety plan atleast once in every three months and written record shall be kept in the premises for the inspection of fire services.
4. Good House keeping must be maintained within the premises.

Remarks: Adequate Fire precautionary measures be adopted in consultation with local Fire Officer during annual day function or any other function where temporary structures and Pandals are to be erected.



[Digitally Signed by Sanjeev Kumar on 06 Jun 2025]

Chief Fire Officer, Fire
Govt. of Himachal Pradesh